

Receiving Report

Parts Received From 11-10-16 to 11-10-16

Batch #	Part #	Description	WH Code	Date Rec'd	Quantity	Part Cost	Unit Measure	Total Cost
PO Number:		1617CED						
33407	34020001	LAMP, INC. 200W/A23/MIF, 4420	19	11/10/2016	60	\$2.08		\$124.80
33407	36402000	TUBE, FLOUR. FB40CW/6, 4420	19	11/10/2016		\$4.25		\$255.00
33407	34150900	LAMP, HID, M1500/BU-HOR, 4420	19	11/10/2016		\$21.43		\$514.32
33407	36401200	TUBE, FLUOR. F40T12CW, 4420	19	11/10/2016	300	\$1.30		\$390.00
33407	36320800	TUBE, FLUOR. F32T8/SP41, 4420	19	11/10/2016	600	\$1.10		\$660.00
33407	34006000	LAMP, INC. 60W/M.I.F., 4420	19	11/10/2016	192	\$1.60		\$307.20
33407	34030100	LAMP, INC. 300W/MOG/IE/130V, 4420	19	11/10/2016	24	\$4.16		\$99.84
Subtotal for PO:								\$2,351.16